

Today's Ethernet




FIG. 1




FIG. 2




FIG. 3




FIG. 4A




FIG. 4B




FIG. 4C




FIG. 4D




FIG. 5A




FIG. 5B




FIG. 6




FIG. 7




FIG. 8




FIG. 9A

Repeater
908




FIG. 9B




FIG. 10




FIG. 11




FIG. 12A




Fig. 12B




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17.




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




Fig. 23

2400




Fig. 24A





Fig. 24B



2500

Fig. 25A

2550




Fig. 25B




Fig. 26





Fig. 27



2800

Fig. 28

2900




Fig. 29




Fig. 30